BOTEN Test report 05.09.2026 17:03:35

Check company: ----------

Tel: ---------- Address: ----------

Fax: ---------- Checker: ----------

Data of customer

Tel: ---------- Company: ----------

Fax: ---------- Name of customer: ----------

Fault description: ----------

Class of model: ----------

Model: ----------

Manufacturer: ----------

Test result

Oil pump model:319-0678

Test name	Pulse width	Speed	The measured	Standard quantity	IMV duty cycle	ZME current	
启动	23.0	100.0	32.8	25.0±10.0	80.0%	----------	✔
供油效率	25.0	300.0	106.5	95.0±15.0	80.0%	----------	✔
IMV1	20.0	800.0	224.7	220.0±70.0	50.0%	----------	✔
IMV2	4.0	800.0	0.0	5.0±5.0	----------	----------	✔

☐ Before repair ☑ After repair